





Model / Modelo / Modèle T4797-FL-LHP▲

Optional:
Pressure balance cartridge RP46074 can replace RP73598.

Opcional:
El cartucho RP46074 para balancear la presión puede reemplazar el RP73598.

Facultatif :
La cartouche à équilibrage de pression RP46074 peut remplacer le modèle RP73598.



▲Specify Finish
Especifique el Acabado
Précisez le Fini